




CQS 0.1 - 0.4mm / CQS 0.1 - 0.5mm / CQS 0.4 - 0.8mm
CQS 0.5 - 1.0mm / CQS 0.7 - 1.2mm / CQS 1.0 - 1.6mm
CQS 1.0 - 2.0mm / CQS 2.0 - 3.25mm

ColorQuartz IC Inducast



ICP D04




ICP D05



ICP D06



ICP D07



ICP D40



ICP D43




ICP D60




ICP D61



ICP D62




ICP D63



ICP D64



ICP D69



ICP D71




ICP D74



ICP D108



ICP D112



ICP D113



ICP D115



ICP D118



ICP D167




CQS 0.1 - 0.4mm / CQS 0.1 - 0.5mm / CQS 0.4 - 0.8mm
CQS 0.5 - 1.0mm / CQS 0.7 - 1.2mm / CQS 1.0 - 1.6mm
CQS 1.0 - 2.0mm / CQS 2.0 - 3.25mm



ICP D170



ICP D727



ICP D729




ICP D777



IC 2



IC 3



IC 4



IC 5




ICD G5



ICD GR3




ICD EB4



ICD BL10



ICD BR10



ICD GR11

ColorQuartz IC Inducast

Because of the natural stone grain, slight differences may appear between deliveries of different batches, samples and charge numbers.

HM-PPW / Merkury Sp. z o. o.
ul. Słowackiego 4 • 68-200 Żary
tel. +48 68 363 02 50 • fax +48 68 363 02 53
e-mail: office@hm-ppw.pl • www.hm-ppw.pl